QUICK REFERENCE GUIDE

Bumper Brackets

		Bumper Brackets						
Model	Year	Height	P/N	Base Kit	Front	Rear	Rear BB	Notes
CHEVY								
Pickup 1500/2500 2/4WD	88-94	3"	C9357	\$176.95	Х	C9950	\$62.95	1, 3, 4
·	95-98	3"	C9356	\$191.95	х	C9950	\$62.95	1, 3, 4
Pickup 1500 2/4WD	99-00	3"	C9355	\$307.95	X	X	402.00	2, 3, 4, 8, 13
•	01-02	3"	C9354	\$307.95	Х	Х		2, 3, 4, 8, 13
	99-02	1.5"	C9154	\$159.95	Х	C9908	\$44.95	2,3,4
	03-05	3"	C9353	\$342.95	Х	X		2, 3, 4, 8, 13
	03-05	1.5"	C9153	\$159.95	Х	C9908	\$44.95	2,3,4, 13
	06-07 CL	3"	C9352	\$385.95	Χ	X		2, 3, 4, 8, 13
	06-07 CL	1.5"	C9152	\$165.95	Х	C9908	\$44.95	2, 3, 4, 13
	07-13	3"	C9350	\$374.95	Х	X		10, 11, 12, 13
	07-13	1.5"	C9150	\$149.95	Х	C9909	\$49.95	3,12, 13
T. 0/ /C /D	14-16	1.5"	C9151	\$179.95	Х	X	¢00.05	13, 20
Tahoe/Yukon/Suburban/Blazer 1500/2500 2/4WD	92-94	3"	C9317	\$199.95	X	C9919	\$99.95	1, 3
	95-98	3"	C9316	\$199.95	X	C9919	\$99.85	1, 3
Tahoe/Yukon/Suburban/Blazer SUV 1500	00-05 07-10	3" 2"	C9315 C9251	\$339.95 \$319.99	X	X		3, 8 3, 12
Pickup S10/ZR2	94-97	2"	C9231	\$176.95	X	X X		
Pickup 310/2R2	94-97 98-04	2"	C9202	\$176.95	X X	X		3, 4 , 6, 7 3, 4 , 6
Blazer/Jimmy S10/ZR2	98-04	2"	C9201	\$207.95	X	X		3,4,6
Trailblazer/Envoy 4.2L	02-09	2"	C9212	\$368.46	X	x		3, 7, 0
Colorado/Canyon 2/4 WD	15-16	1.5"	C9157	\$165.95	X	X		
Colorado/Carryon 2/4 WD	04-12	1.5"	C9157	\$239.95	X	C9906 or	\$39.95 or	3, 4, 14, 15, 16
	04 12	1.5	C)133	\$237.75	^	C9907	\$53.95	3, 4, 14, 13, 10
DODGE								
Ram 1500 2/4 WD	09-16	1.5"	D9150	\$139.95	Х	Х		3,21
Ram 1500 4WD V8	06-08	3"	D9345	\$355.95	Х	х		4
		1.5"	D9151	\$165.95	Х	х		3,22
Ram 2500	14-16	1.5"	D9152	\$319.95	Х	Х		22, 23, 24
Ram 3500	13-16							
FORD								
F150/Supercrew/F250 LD 2/4WD	97-03	3"	F9385	\$199.95	Х	х		3, 4
	97-03	2"	F9285	\$187.95	X	X		3, 4
F150 2/4WD w/o factory hitch	04-05	3"	F9383	\$365.95	Х	Х		3, 4, 9
F150 2/4WD w/ factory hitch	04-05	3"	F9384	\$365.95	Х	Х		4, 9
F250/F350 Super Duty 2/4WD	99-03	3"	F9387	\$334.95	Х	Х		1, 3, 4
Ranger 2/4WD	98-00	3"	F9378	\$175.95	Х	Х		3, 4, 5
JEEP								
JK Wrangler	07-16	2"	J9210	\$119.99	n/a	J9211	\$58.95	17, 18, 19
TJ Wrangler	97-06	3"	J9300	\$114.22				
	97-06	2"	J9200	\$108.75				
	97-06	1.25"	J9120	\$94.95	1.5	SOO.		
YJ Wrangler Manual	87-95	3"	J9320	\$95.99		0.00	A 200 C	
	87-95	2"	J9220	\$89.99		200	Ave to a	100
YJ Wrangler Auto	87-95	3"	J9321	\$103.49	40	-	A CAN	
	87-95	2"	J9221	\$97.69				
YJ Wrangler Auto/Manual	87-95	1.25"	J9121	\$89.95		-		
CJ-5 / CJ-7 (manual only)	72-86	3"	J9330	\$94.06	ET and	407		• 1
	72-86	2"	J9230	\$89.74	17/199	73/16		
THE IS A CHIEF DEFENDENCE CHIEF	_				111111			•

THIS IS A QUICK REFERENCE GUIDE.

FOR COMPLETE KIT DETAILS SEE ACTUAL APPLICATION PAGES.

Bumper Brackets

x = Included blank = Not Included Part # = Not Included but available separately

* For quick reference only. For complete kit information look in application listing.

Notes

- 1. Will not fit vehicles with a diesel motor.
- Will not fit heavy duty model.
- 3. Rear bumper brackets are for appearance only. The rear bumper cannot be used for towing
- 4. Fits standard cab, extended cab, crew cab, long box and short box.
- Manuals require shifter extension kit # F9802 (Mazda transmissions only)
- Vehicles equipped with Vortec V6 may require modification of air intake.
- 1994 model requires additional part #C9807
- Manual transmission models require shifter extension # C9806
- Will not work with lifted suspension systems that relocate rack and pinion steering system.
- 10. Will not fit regular cab long box configuration. 11. Will not fit applications with manual transfer case shifter.
- 12. Will not fit 07 Classic model. 13. Will not fit Denali models.

- 14. For automatic transmission models only.
- 15. Trimming of front bumper plastic valence or frame required for front bumper relocation.
- 16. 2008-12 models require rear bumper bracket kit C9906, and 2004-07 models require C9902.
- 17. Fit both 2 and 4 door models.
- 18. Manual transmission models will require shifter boot and floorboard modification to ensure full shifter engagement.
- 19. Not recommended for 2011 or newer models with manual transmissions and new style interior due to shifter and floorboard modification required.
- 20. Will not fit 07-13 models.
- 21. Will work on 3.0L diesel equipped trucks.
- 22. Will not fit Mega-Cab models.
- 23. Some long bed configurations may require additional mounting hardware
- 24. Goose neck hitches may require an extended length ball. Not recommended for use on vehicles equipped with fifth